

4 - APR 1940

as
ified

Chief Surveyors _____

Received from Chief Surveyors _____

SHIP'S NAME "YOKOHAMA MARU" Report Lon. No. 108303

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey _____ When due _____

The class is subject to the starboard screw shaft being specially examined in way of stern-bush aft bearing before the end of 6,40.

The Owners now write they have decided to discontinue the vessel's class.

It is submitted the class of this vessel be withdrawn from the Register Book and Three Dots(...)inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class

Insert ...



2020
[Signature]

Lloyd's Register
Foundation

3.4.40.

W1359-0003

Rule length

Locker