

Oct 4 -

1940

## REPORT ON MASTS, SPARS, AND RIGGING.

Mr. Buchanan

Having, in accordance with your instructions, examined ~~the~~ Masts, Spars, and Rigging, and Iron Work of same, of the

S. West Pool

I have to report that I found Foremast Rigging Including Shrouds  
 & Stay Stays & Fore Stays in Bad Shape would condemn same  
 Turnbuckles after being freed up are usable & Satisfactory  
 Main Mast Rigging in Bad Shape would condemn same  
 Turnbuckles after being freed up are usable & Satisfactory  
 Main Mast Stay Stays in Bad Shape would condemn same  
 Turnbuckles 3 usable & Satisfactory 3 missing  
 Main Mast Rigging in Bad Shape would condemn same  
 Turnbuckles usable & Satisfactory 6 Turnbuckles No Good  
 Main Mast Rigging Including Shrouds & Stays Bad Shape condemn  
 Turnbuckles in Good Shape & Satisfactory <sup>same</sup>

See *Life*

*the Surveyors,  
Lloyd's Register of Shipping,*

S. C. Matthews  
Skip Rigg

Lloyd's Register  
Foundation

W136-0025