

S/S Westpool.      Seattle Wash. Rept 747

It is submitted the Seattle Surveyors be informed  
it is concluded, 2 top end bolts and nuts and 2  
end bolts and nuts have been put on board  
have gear, as this is not mentioned in their report  
urveyors should state if this is so.

W136-0038

JWD.

JK  
8/1/19.

Lloyd's Register  
Foundation