

W1360-0076

Nasbek.Nov. 1948

It is concluded that the tenacity of the filler plates in the Rollers is 47 to 53 kg. per m<sup>2</sup> and that the riveting of the manhole compensation plate is in accordance with the amendments shown in the

Sketch which accompanied the Surveyors letter dated 15/1/30 but these points should be confirmed.

L. 79/30

WDA B.M. 22/8/30