

Chief Surveyors _____

Received from Chief Surveyors _____

EL'S NAME STEEL S.S. "AFEL"

Report P&L

No. 3387

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey _____

When due _____

Kedge Anchor tested by American Bureau Surveyors

Part of the chain cables are of Cast Steel, tested as required.

❖ 100 A.I. (steel)


2 Dks (steel) and wellframes.

Cell DB 279' 1380 t. MT 24' 748 t. FPT 144 t. APT 100 t.

FR. SBH. Cem A+C.P. P39 B 122' F 43'.

aeB.
3.10.19

20/1/19
It is concluded, the bulkhead ^{see letter} stiffeners are as approved but the
Surveyors should be requested to state if this is so.



Lloyd's Register
Foundation

W1362-0056