

S.S. "ANAMBA"

This vessel was built in 1902 and her class was withdrawn from the Register Book and three dots inserted in lieu thereof.

A cablegram has now been received from the Singapore Surveyor stating that the Owners desire the vessel to be reclassified.

It is submitted the Singapore Surveyor be informed that in order to render the vessel eligible to have her class reinstated in the Society's Register Book, it will be necessary for the requirements of the 2nd Special Survey No.3 to be fully complied with and for the vessel and her equipment to be favourably reported upon.

The necessary particulars from the First Entry report should be forwarded for the Surveyor's guidance.

Bpt

4.12.22

Ans.

*For Mr. J. A. Hill
to write Eng.*

Ans. 5.12.22



© 2021

Lloyd's Register
Foundation

W1365-0774