

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

st Report, No.

Port

Particulars of Classification
precisely as in
CHARACTER.
for Special Survey.
Date of last Survey and of
Periodical Surveys.

+ 7.1. 2,21

er Dred

T. 737.

RS.

8/20/7

922

LLOYD'S REGISTER

Lloyds Register of British and Foreign Shipping,

4 APR 1922 East London, MARCH 10th. 1922. 191

IS

LR-16/22.

HOPPER DREDGER "AGNES"—WITHDRAWAL OF CLASS.

Dear Sir,

I am in receipt of your letter "S" of 10th. Ultimo
notifying me that the class of this vessel has been withdrawn,
and (s.s.) inserted in lieu thereof.

have notified the Divisional Superintendent Railways and
Harbours accordingly.

I am, Dear Sir,

Yours faithfully,

J. Morrison

SURVEYOR TO LLOYD'S REGISTER.

Secretary,

Lloyd's Register of Shipping,

LONDON. E.C.3.



© 2021

Lloyd's Register
Foundation

W367-0173

Section 28)

or Repair Fee (if any)

Fees applied for,

Referred to Mr. S. A. Hill

CRD
-4 APR 1922

SECTION 8, TOWN OF ROYAL

VALLEYVIEW

THE TOWN OF

VALLEYVIEW

has been the subject of a recent report

received from the

authorities of the town of

Valleyview, that the

SEAL TO THE TOWN OF



© 2022 Lloyd's Register Foundation
Lloyd's Register
Foundation

SECTION 8, TOWN OF ROYAL

VALLEYVIEW

Report,