

Did the Surveyor examine all the mountings of the Main Boilers? .....

W137 00 23

s regretted this report has been  
yed through oversight.

L. E. Hansen

If so, did the Surveyor examine the generators, motors, switchgear, ca