

The class is Subject to the
DONKEY BOILER
 not being used again.

2E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Willemsplein

Rpt.

Rpt.

No. 23824.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 3

This Survey, due 4.35- partly held at _____ now
 completed, and the following repairs carried out (due to groundhog) and
 wear & tear):-

Screw shaft found cracked at middle.
 Shaft renewed.

Stem tube and bush renewed.

Crank shaft life & bearings reinstalled.

L.P. piston rod renewed.

It is submitted the vessel is eligible to remain as classed, with
 notation of +LMC 7.35- as recommended.

S. 7.35-

Subject to the
DONKEY BOILER
 not being used again.

L.F.
 2/8/35.



© 2020

Lloyd's Register
 Foundation

W 137 - 0028