

"WHINNYFOLD"

A Reclassification Survey 3rd.S.S.  
No. 3 has been completed except that a number of shell  
plates require to be renewed.

The renewal of these plates was  
postponed as the necessary licence from the Ministry of  
Shipping could not be obtained.

Notations of 100A1 "Steam Trawler"  
(Reclassification contemplated) and 'Examined 1.41' (12 mos)  
have been assigned.

For the maintenance of the vessel's  
class it will therefore be necessary for the worn shell  
plates to be examined by 1.42, (when an ordinary condition  
survey can also be made.)



© 2020

Lloyd's Register  
Foundation

11/37-0078

28.11.41

necessary for

examined record  
1.1.41