

Ship Surveyor.....

Received from Chief Ship Surveyor.....

1E

WHINNYFOLD"

Rpt.

Hul

No. 51056

The Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also pointing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points noted in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

The classification of this trawler was withdrawn in June 1939 at the Owners' request.

A Reclassification Survey, 3rd S.S. No. 3, has been partly held.

Some shell plates require to be renewed, and some others further examined.

The Ministry of Shipping, however, would not grant a licence for the renewal of the plates, which are not to such an extent that the vessel cannot be reclassified without this being done.

It has been agreed that when the Surveyor Reclassification has been completed, <sup>in other respects</sup> notations of "100A1 Stm trawler" (Reclassification contemplated) and 'Examined (with plates)' will be assigned on the understanding that the worn plates will be examined periodically and renewed as soon as possible.

The HULL Surveyors now report the trawler placed on a slipway, bottom coated, and the Reclassification Survey completed, except as regards the renewal of the badly worn shell plates.

The shell plates which require to be examined hatchway of moulding have been built up with electric welding, and the moulding re-fitted.

Repairs or renewals have been effected to other shell plates, hatchway, framing, bulwarks etc.

The Surveyors recommend the notations "100A1 Stm trawler" (Reclassification contemplated) and 'Examined' will be assigned pending completion of the Reclassification Survey. *valid for 12 months (see letter)*

It is submitted these notations be assigned, subject to shell plates E.3, E.8, F.9, F.10 and G.10 being examined periodically and renewed as soon as possible.

Insert in S.R.L

"100A1 "Stm Trawler" (Reclassification contemplated).

Exd. 1.41 - for 12 mos.

Shell plates as stated to examine

periodically and renew as soon as possible.

© 2020

Lloyd's Register Foundation

7800-18111