

No. 17.

"Whimpyfold"

F.E.

Received by Chief Ship Surveyor 17/8/08

Received from Chief Ship Surveyor .....

VESSEL'S NAME M. S. S. Antonio Rpt. Kul No. 20422

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

## CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>8" in lieu of 7"</u>	<u>not required</u>
Spar Sheerstrake . .	<u>✓</u>	<u>✓</u>
Description of Framing:— <u>Ordinary, increased to compensate for omissions of rivet frames.</u> (viz., ordinary, deep, zed, channel or bulb-angle)		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100A1 (Kul) Steam Trawler as recommended

+ 100A1 (Kul) Steam Trawler  
18x

N.B. A.P.T. 34 D.T.F. 15 336  
BK 8" H.B.A. Lloyds A+B.C. ccm.



R.B.M.  
© 20/8/08

Lloyd's Register  
Foundation

Angles on Upper Edge .....	✓	Angle on ditto .....	✓
Spacing .....	✓	Tie Plates .....	✓