

S. S. Bristol

This vessel, completed in February last has not been built under survey. *on May 1st 1916*

The Philadelphia Surveyor reports the particulars of scantlings of the Engines & Boilers which he states are given by the builders as being correct. The steel plates of the boilers were tested by U. S. Officials who also are stated to have witnessed the tests of the boilers & safety valves.

All details are in accordance with the Society's Rules, but no survey has been held by any of the Society's Surveyors on the machinery. The Surveyors however state that the scantlings and construction were noted from time to time during construction but no official survey was held.

It is submitted that when an opportunity is given for the machinery & boilers to be examined throughout by a Surveyor to this Society and the particulars in the Report are verified by him from actual inspection, and the machinery & boilers found to be in good condition the vessel will be eligible to have the record & MC with date but without the Special Survey mark.

Lo: -16/6/16  
to Mr. Drench

J. M. 9/6/16

J. R. R.

© 2020

Lloyd's Register  
Foundation

W137-0123