



Lloyd's Register of British & Foreign Shipping,

97 & 98; Scottish Provident Buildings,
Donegall Square, West,

Belfast, 7th March 1908

The Secretary
Sir

LLYD'S REGISTER
LONDON.
REC^d 9 MAR 1908
ANS^d

Reference

With reference to the note in the Closing Letter of the 6th inst. regarding Mr. Milton's Fuel Entry Report on the S.S. Incauca. I beg to inform you that the thickness of the bulkhead plating has been wrongly stated as $\frac{7 \text{ to } 6}{20}$. This should be $\frac{8 \text{ to } 4}{20}$.

I am, Sir
Very obedient servant
R. J. Sewell



© 2021

Lloyd's Register
Foundation

0371 0002

Referred to the Chief Ship Surveyor.

CSA

MAR -9 1888

ap for Mr. S. A. Hill to note.



© 2021

Lloyd's Register
Foundation