

9-OCT-1920

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *SR T/s. "Alps Mars"* Rpt. *Kob* No. *2951*

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/3/92.

DAMAGE. + Condition.

Damage through heavy weather. (see YKA 2701)

How repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							
Other items:-	Repairs effected to deck plating, No 1 hatchway coamings. etc. as found necessary.						

Vessel examined in dry dock + minor repairs effected on account of wear & tear.

It is submitted the vessel is worthy to remain as classed with record of Survey 8.20 as recommended. without special conditions -

100 A1 Shelter deck with fbd. } Without
8.20 Kob } etc.

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.

It is concluded that the joining shackle which has been supplied is a properly tested shackle but the Surveyors should state if this is so -

Lloyd's Register Foundation

7.10.20
W1371-0139