

Received by Chief Ship Surveyor

1/2/13

Received from Chief Ship Surveyor

VESSEL'S NAME

H S Lug 'Arany'

Rpt.

Ply

No.

5762

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

It is submitted that before this case receives the consideration of the Committee this report should be returned to the Plymouth Surveyor, and he should be requested to complete it by filling in the length of the vessel, depth (d), proportions and the weight of the stock of the 3rd ~~lower~~ anchor.

He should at the same time state what arrangements have been made for fitting the 6 x 6/20ths bulb plate stiffener on the after peak tank bulkhead.


His attention should also be called to the fact that the Builders stated on the 9th January that it was not intended to use the fore peak as a tank, and in view of his having tested this space and forwarded the capacity, he should state clearly whether it is intended to use this as a tank or not.

Ln. Ry 1/2/13

M. 29811

1. 2. 13.

© 2021



Lloyd's Register  
Foundation

W1373-0169