

to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME WALMER CASTLE Report 9th No. 64316**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Survey General Examination When due (1st S.S. No 1, due 11,40)
& alterations & closing of T.O.

Subject to indented tank top plating in No 2 hold, indented keel plate No 3, shell plates A3 & 4 (P+3) & F4, 5, & B(ss) being dealt with at the Owners convenience

Indented shell plate E6(ss) requires to be dealt with at the first convenient opportunity

ARL
16/9/41.

Amend in RB. 1 Plk & shellor dk

to 2 Plks

& GBH
(coll 4 5 1/2 dk)
5 " 2 " "

to

GBH
(coll 4 1/2 dk)
5 " 2 " "

note. the closing of the T.O. does not affect the draught of the vessel

© 2020

Lloyd's Register
Foundation

W138-0162