

11314

WOP2HAP

M.V. "WALMER CASTLE"

88033

500
320
100

REPAIRS.

FOR^D. DYNAMO ENGINE - fwd. and after cylinder liners renewed wear & tear
AFT. " forward cylinder liner renewed. wear & tear

NOTE: - Compressors of dynamo engines not opened up at this time for examination -

ELECTRICAL INSTALLATION:-

The electrical installation examined under working conditions, Generators, cables, and fittings on Main Switchboard and in distribution boxes examined, insulation tests made on all circuits, all found to be satisfactory.

W.D.



to complete

accordance with the requirements

Nov 1914

Noted
M. J. 14 14 14
Submitted the drawings to be
checked whether he examined the
Crank shaft of the Compressor
of the Centre Dynamo Engine

W.D.
17/11/14

17/11/14

