

71'S
COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

Enclosures.

8th July, 1919.

Dear Sir,

I have to acquaint you that the Auxiliary Twin Screw Steamer "ESQUIMALT" was surveyed at Port Said at the beginning of this year, and the Surveyor reported that the starboard main engines were so seriously damaged that they could not be repaired, and also that a second-hand donkey boiler had been purchased and placed on board at Port Said. The vessel proceeded on her voyage with only the port engines working, and subsequently arrived at Malta, where she was surveyed on account of damage sustained through stress of weather.

A copy of the Surveyor's Report is enclosed for your information, and as it would appear from the Shipping Papers that the vessel has left Malta in tow for Marseilles, I shall be glad if you will give the case attention on her arrival and let me know what is being done in the matter.

I have also to enclose a copy of a letter which was addressed to the French Minister of Marine on the 16th April last, to which no reply has been received.

I am, Dear Sir,
Yours faithfully,

Secretary.

P. Jones Esq.,

MARSEILLES.



© 2021

Lloyd's Register
Foundation

W1382-0068