

22 MAY 1919

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME Wood Aux. Tw/S.S. "ESQUIMALT". Rpt. Mlt. No. 984

the remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey


*Damage*

This vessel is reported by the Malta Surveyor to have sustained damage through stress of weather, and the Surveyor recommends the caulking of the seams & butts of the planking at the bows be hardened up & payed, & caulking of the butts of the upper deck planking be hardened down & payed.

The Surveyor further recommends that the beam knees be examined when the cargo is discharged.

It is submitted the vessel appears worthy to remain as classed, without fresh record of survey, subject as recommended.

*as now subj't  
do!*



© 2021

Lloyd's Register  
Foundation

22. 5. 19

W1382-0074