

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When landed in at Local Office... Port of London

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19

53121 on the Wood, Iron or Steel Sc. Gr. "Bradford City" Master W. Griffiths - 19

TONNAGE:-

GROSS 5261

UNDER DEK. 4817

NET 3178

Built at Stockton

By whom Craig

Taylor & Co. Ltd. When 1919 - 3

Owners W. R. Smith & Sons (Ingrs)

Port belonging to Bideford

Owners' Address

(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

feet; }

total capacity tons. FPT

tons; APT

tons; MT

feet

tons. }

N.B. All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 17447 Port Bury

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the extent of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.  
\* for Special Survey.  
Date of last Survey and of  
Periodical Surveys.

+100A1  
1-20.

Years  
Assigned  
and  
expired.

Machinery and Boiler  
Survey  
(including date of N.B., if any).

FLMC 8-19.

T.S. 1-20.

Society's Freeboard (if assigned) as painted on Ship and now verified

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why were declined? Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR

OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
ed ... ..								
red and Fair'd or Repaired ... ..								
or Repaired in place ... ..								
CONDITION OF THE	Stringers .....	Dblg. Plates under Sounding Pipes .....				Copper, or Y.M. of Wood Vessels..... (State if on Felt.)		
Inner Bottom Plating.....	Inner Bottom Plating.....	Engine Room Skylights.....				When put on, Month .....		
State if Tanks have been examined inside .....	State if Tanks have been examined inside .....	Coal Bunkers, Open'gs, Lids, &c.....				Year .....		
State if Tanks now tested .....	State if Tanks now tested .....	Scuppers .....				Boats.....		
Bulkheads .....	Bulkheads .....	Cargo Hatchways .....				Masts, Yards, &c.....		
Ceiling .....	Ceiling .....	Hatches .....				Condition, how ascertained.....		
Cement or Asphalt .....	Cement or Asphalt .....	Planking .....				(State if wedges removed)		
(State which.) .....	(State which.) .....	of Wood Vessels.....				Sails.....		
Rudder .....	Rudder .....	Caulking .....				Equipment letter .....		
Steering gear and its connections.....	Steering gear and its connections.....	Treenails .....				Anchors, No. of .....		
Windlass.....	Windlass.....	Breasthooks & Stemson .....				Cables (State if now ranged).....		
Have Pumps now been examined and found effi-	Have Pumps now been examined and found effi-	Transoms, Pointers, & Crutches ditto.....				,, length..... size		
cient? .....	cient? .....	Timbers of Frame at openings ditto.....				(on board) .....		
Have Sluice Valves now been examined and found	Have Sluice Valves now been examined and found	Ditto ditto at other places ditto.....				,, Rule length..... size		
efficient? .....	efficient? .....	Stringers, Clamps & Shelves .....				Hawser & Warps .....		
Have Watertight Doors now been examined and found	Have Watertight Doors now been examined and found	Salting .....				Standing & Running Rigging.....		
efficient? .....	efficient? .....	(State if examined.) .....						

ul Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptnD15, &c."

Survey Fee (per Section 25) .....	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 25) .....	£	:	:	19.
Travelling Expenses (if chargeable) .....	£	:	:	Received by me,
Second Surveyor's Fee (if any) .....	£	:	:	19.

Committee's Minute FRI. SEP. 24 1920

Character Assigned

Withdraw class  
+ insert

Surveyor to Lloyd's Register of Shipping.

General Committee  
Thursday 30<sup>th</sup> September 1920.

Lloyd's Register  
Foundation

W1394-0020