

3.3. China Rec 56475-

It is concluded That The sea connections
are fixed sufficiently high on the
Ship's side to be seen without lifting
The shockhold plates, but it is
submitted That The Newcastle
Surveyors Should be requested
to state if This is so.

ARRR
17.4.09

W: - 17/4/09



© 2021

Lloyd's Register
Foundation