

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

AMATIAN

Report Gal

No. 4222

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Docking

~~When due~~

Subject to shell plate F.3 (p.s) E.W. 5,39 being specially examined at the next dry docking.


The Surveyors should be referred to Circular 1707A and requested to state whether the condition regarding the E.W. repair to the shell plate can now be recommended to be deleted.

S.O.N.Y.N.

22-4-42.

W141-0194

15 APR 1942



was
14.4.42

Lloyd's Register
Foundation