

Do. of Bridge  
Do. of Foremast  
Do. of Houses on  
Do. of excess of  
Do. above Crow  
Main Deck

ed by Chief Ship Surveyor 13. 6. 10.

Received from Chief Ship Surveyor .....

SEL'S NAME SS "No. 524" by Messrs Otto Johansen Rpt. Rot. No. 6662

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey FIRST ENTRY.

It is submitted that before this case receives the consideration of the Committee, the London Surveyors should be informed that this vessel has been towed to Yarmouth, at which port it is reported she will be fitted with her machinery, and to complete the survey on the hull, the E. & B. casing tops require to be riveted and the casing stiffeners to be completed, and the strong beams and pillars between E. & B. space to be riveted. They should be requested to give the case the necessary attention, and on completion of the survey to forward a report on Form 8 in the usual manner, with a view to the classification of the vessel.

Dr. 14/6/10.

RM RM  
14/6/10



© 2021

Lloyd's Register  
Foundation

W1415 0158