

fees paid

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Single Sc. "AELYBRYN"

Rpt.

Sld.

No.

32349

(Rpt.1)

"

32349

(Rpt.8)

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24592.)

1st Long. No.	14051	Depth "d"	24.69
2nd Long. No.	37056	Proportions = $\frac{L}{D}$	11.36
Framing Bulb angle frames as approved	Sheerstrake		As approved

The Sunderland Surveyors report this vessel examined in dry dock, on account of damage through striking a quay, repairs and renewals to shell plating, framing, and minor repairs effected.
This is a sister ship to the "GEMSTONE"

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **LOCAL "With Freeboard"**

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.

1 Dk. and Shelter dk.

Cell.DB 349' 1114t, FPT 204t, APT 168t.

FK, 6BH(Coll.BH to Shelter dk., 5BH to 2nd Dk.) cem., Lloyd's A & CP.

F 39'

O.L. 428'.



© 2021

Lloyd's Register
Foundation

Handwritten signature
 22.4.28

W142-0114

FB