

Sent to Chief Ship Surveyor 4.9.06

Received from Chief Ship Surveyor _____

VESSEL'S NAME M. J. S. DeltaRpt. Cbo No. 81

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Nature of Survey _____

This vessel is reported by the Colombo Surveyor
to have sustained damage to her shell plating through collision whilst
at her moorings Temporary repairs have been effected to his satis-

faction to enable her to proceed on her voyage to Bombay.

The Surveyor recommends that the vessel be placed in dry
dock for further examination on her arrival at Bombay.

It is submitted action be deferred pending the receipt
of a report from the Bombay Surveyor, S - Belfast.

W.D.
4.9.06
C.D.



© 2021
W.D.
4.9.06

Lloyd's Register
Foundation

W1426-0057