

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

St "Duster."

Report

Low.

No. *75937*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Screwshaft

When due


7.13.

This vessel's screwshaft became due for first biennial survey at the end of last month.

In reply to the usual notice the owners write to say they do not intend to continue the vessel's class.

Submitted the class be withdrawn and three dots inserted, indicating withdrawal at owners request.

*Withdraw class.
Insert (...)*

Hev  *28.8.13*

E. L. G. *ARK*



© 2021

Lloyd's Register
Foundation

WT431-0200