

Is the Screw Shaft Tunnel watertight

None.

Is it fitted with a


Ph...

of "Laci."

Hull Rpt No 34531

It is submitted, that the Hull Surveyors should be requested to state, whether 2 main bearing bolts have been supplied by the Manufacturers, as spare gear as required by the Rules.

Mr. 279/11



Lloyd's Register
Foundation
2079/11
JWA
JWA

W1443-0067

Material Steel Thickness 1/6" Pitch of stays 16 x 15 How are stays secured Interwoven Working pressure by rule 222 Material