

(3m,4,5.)

Received by Chief Ship Surveyor

8/8/05.

Received from Chief Ship Surveyor

VESSEL'S NAME

SEA LIGHTER

"Forestal"

Report

BAL.

No.

1373.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Damage

The Buenos Aires Surveyor reports that this vessel is undergoing repairs at his port in consequence of grounding, but he is informed by the Owner per letter attached that he wishes the vessel's class to be withdrawn from the Register Book.

It is submitted the vessel's class be withdrawn from the Register Book, and three dots inserted in lieu thereof, indicating withdrawal of class at Owner's request.

Withdraw class.

Insert (...).



© 2021

Lloyd's Register
Foundation

W1449-0017