

supported by each stay 196" Working pressure by rules 182 Material of Front plates at bottom

No. 919. Made by J. Abernethy & Co L^d - Aberdeen
Admiralty Difter "FLICKER" (A. Hall & Co. - YN 553)
Abn. Report No. 12108.

It is submitted that further action in the case is unnecessary ^{as} ~~until~~ this boiler is ~~fitted on~~ a classed vessel.

W. J. H.
Date 6/9/18

Entered in "Unclassed" Boiler Book. Lloyd's Register Foundation
W1449-0173