

1

11 DEC 1942

Sent to Chief Surveyors.....

Received from Chief Surveyors.....


VESSEL'S NAME "ASTRELL" REPORT Bos. No. 3769

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Damage When due

Subject to shell plate No.3 in 2nd strake below sheer (p.s.) E.W. and reinforced 1.42, being specially examined by 1.43, and to the ~~renewed~~ ^{RECOVERED} bower anchor and 45 fathoms of chain cable being examined, and replaced on board at the first opportunity, if found in order.



© 2019

Lloyd's Register
Foundation

W145-0095