

1

Sent to Chief Surveyors 4. 1. 13

Received from Chief Surveyors

VESSEL'S NAME Itl Sc Sp "G. L. P. A"

Report London

No 75255

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Screw shaft

When due 5. 12.

The screw shaft became due for survey in May last & has not yet been seen.

The owners now state that <sup>they</sup> ~~they~~ wish to retain the class of the vessel.

Submitted the vessel's class be withdrawn from the Register Book, & 3 dots inserted in lieu thereof indicating withdrawal of class at owners' request.

Withdraw Class  
Insert . . .

50/8 AWD

4. 1. 13

 2021  
Lloyd's Register  
Foundation