



LLOYD'S REGISTER OF SHIPPING,

154, CALIFORNIA STREET,

LLOYD'S REGISTER
NEW YORK
REC'D OCT 29

SAN FRANCISCO

ANS'D

October 22nd, 1917.

Dear Sir,

In reply to your letter of October 15th,
kindly note that the bridge side plating of the
new Steamer "FREDERIC R. KELLOGG", Report No. 2550,
is .42" in thickness and not .40" as incorrectly
stated in the First Entry Report.

With apologies for this clerical error,

Yours faithfully,

Arnold Bennett.

The Secretary,

NEW YORK.

AB:MA.

Send Law



© 2021

Lloyd's Register
Foundation

W1452-0025