

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

8761 90V I

VESSEL'S NAME Wood Aux. Sc. "ITALIA"

Report _____

Lon. _____

No. 86843^a -**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/02.)

Nature of Survey _____

When due _____

The class is subject to 30 fathoms of chain cable being supplied and the remainder of the cable verified with the certificates of test.

The Annual Survey of the oil engines and donkey boiler survey became due 1,22, and a proposal to postpone these surveys for the present was agreed to, subject to the same being carried out before the vessel again proceeded to sea.

The Rio de Janiero Surveyor now states he has been informed by the Owners that they do not wish to continue the classification of the vessel.

It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class
Insert ...

30.7.23.



© 2021

Lloyd's Register
Foundation

W1454-0124