

of Surveyors 12.7.18

Received from Chief Surveyors _____

NAME Sheels West Indian

Report Portland

No. 493

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Survey _____ When due _____

This vessel has the rule number of bulkheads fitted.

100 A.1. *Steel*

2 DLs (*Steel*)

Cell 5B 355' 1166E F.P.T. 1376 a.P.T. 45E

FK. 7BH. pl. Cam. Lign. ated. Pwd. 8115 Fu7

M
13.7.18

*In compliance with the 2" DL Beams are spaced 54" apart
and that the rivets in the 3 riveted bulkheads are 3 1/2 diameters apart.*

M

S/o to 29/7/18



© 2021

Lloyd's Register
Foundation

W1462-0030