

Received by Chief Ship Surveyor 31. 3. 10

Received from Chief Ship Surveyor

VESSEL'S NAME Steelss 'Guerdon'Rpt. AbnNo. 10200

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

&amp; Condition

Damage through Collision at various times during fishing season

now repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....	✓	✓	-	-	-	-	-
Removed and faired or repaired.....	✓	✓	-	-	-	-	-
Faired or repaired in place.....	2	2	-	-	-	-	-

Other items:-

Bulkhead plating, Slanchins & main rail repaired.


Condition. Bottom & rudder examined on Slipway  
& afterwards cleaned & recoated.

It is submitted the vessel is worthy to remain as classed with  
record of Survey 3.10 as recommended

100 A-1. For fishing purposes

3.10 abn.

AR  
31. 3. 10



© 2021

Lloyd's Register  
Foundation