

-3 JUL 1942

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "BAHADUR" REPORT Bom. No. 6832

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

(The 1st S.S. No.3 became due 9,41).

For conditions of class see Endorsement 12.2.42.  
Action has been deferred for dry docking (grounding).  
The BOMBAY Surveyors report (3,42) the vessel placed in dry dock, bottom coated.

Indented keel plates, as above, examined and found efficient.

*No damage from grounding reported.*  
It is submitted the vessel appears worthy to remain as classed with record of docking survey 3,42 subject as above.

As now, subject etc.  
3,42 Bom.

Delete from S.R.L.

Dry dkg (grounding).

SQR 1-7-42



© 2021

Lloyd's Register  
Foundation  
W147-0185

Vessel sunk