

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19

When handed in at Local Office 19

Port of London

No. in
Reg. Book.

Survey held at

Date, First Survey

Last Survey

19

16302 on the Wood, Iron or Steel *Sc Bernay*

Master

When 1918 5

TONNAGE:-

GROSS

UNDER DE

NET

Built at *N. Vancouver B.C.*By whom *Byrd & B. Cold*Owners *Les Amateurs de la Carre*

Owners' Address

(if not already recorded in Appendix to Register Book).

Port belonging to *Amstirk*

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

feet; f

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 1551

Port *Gib*

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+12 A1	1.19	+14 C 5.19
Sailed & Sprayed treated		BS 620
		TS 1.19 C. 1.
		NTB

Society's Freeboard (if assigned) as painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Dbng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt.)
Waterways	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Coamings	Ceiling	Scuppers	Boats
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	Rudder	Hatches	Condition, how ascertained
Caulking of ditto	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)
Rivets	Windlass	Caulking ditto	Sails
Breasthooks & Crutches	Have Pumps now been examined and found efficient?	Treenails ditto	Equipment letter
Transoms	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of
Frames	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Reverse Frames	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	" length size
Floors		Ditto ditto at other places ditto	(on board)
Keelsons		Stringers, Clamps & Shells ditto	" Rule length size
Stringers		Salting ditto	Hawser & Warps
Inner Bottom Plating		(State if examined.)	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and pND15, &c."

Survey Fee (per Section 29) £

Special Damage or Repair Fee (if any) (per Sec. 29) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19


Received by me,

19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned



© 2021

Lloyd's Register
Foundation

W1471-0085