

Temporary repairs now effected
strike plate and overhauling to

CEMENT BOX IN WAY OF
ALUMINUM

Class W

for

Received from Chief Ship Surveyor

VESSEL NAME Steel S.S. "INGOLD". Rpt. Hul. No 31853

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Hull Surveyors report this vessel has sustained damage to shell plating through collision and that temporary repairs have been effected to their satisfaction and they recommend that permanent repairs be carried out at a convenient opportunity.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

100A-1.

5.20 1st

Hull for at fuel

subject



© 2021

2. 6. 20.

Lloyd's Register

W1474-0042