

Do. of Houses on Deck 118.98
Do. of excess of Hatchways 10.33
Do. above Crown of Engine Room
Gross Tonnage 9734.99

Length on Deck from fore part of stem to after part of sternpost 450
Longitudinal Number 41400

By whom built William Be
Owners Australasian

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSSEL'S NAME

27/11/12

Alfred Indara

Report

Slts

No 22043

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the "Classing Committee" the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/92)

Nature of Survey

First entry

When due

+ 100A1 (2nd) Awning deck with foreboard
2nd (U - 1st + 2nd dr pt etc) + Awning Dr (etc - 1st + 2nd in
WB. but D/Ba 64 u 2 + B 151 f 163 976t FPT 122t APT 73t No 2 hold
FK + BK 1, 7 BH, Com. Lloyd A + 60 B 215 F 51 on Awning dr.

M. 2187
27/11/12



© 2021

Lloyd's Register
Foundation

W1474-0095

Angles on upper edge	27 1/2	27 1/2	Angles on ditto	
Spacing	6 1/2	6 1/2	Tie Plates	
BEAMS, Poop Deck, Angle, Bulb, Angle, Plate, Tee Bulb	12	12		