

Gls Report N^o 26934.

It is submitted that action on this Report be deferred
& the Gls surveyor be requested to state if the
thickness of the combustion chamber bottom given
in his Report as $\frac{3}{4}$ " is correct, in view of the
approved plan showing the thickness as $1\frac{3}{16}$ "

JRR

2-9-08

JH.

© 2021
2-9-08

Lloyd's Register
Foundation

W1476-0056