

THE 2ND S.S. No.2 BECAME DUE 6.41

EXAMINED 1.42 - 12 MONTHS

Report to Chief Surveyors.....

Received from Chief Surveyors.....

15 MAY 1942

VESSEL'S NAME..... AUST..... REPORT..... N. Yk..... No. 42236

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Particulars of Survey..... DAMAGE..... ~~When done~~.....

Subject to repairs to upper section of main frames in boiler room and to the cables being ranged at the first opportunity.

WOL
15.5.42

(Docking date)
(3.42)

(H.W)



© 2019

Lloyd's Register
Foundation

W448-0132

Have Sluice Valves been examined and found effi-

Caulking.....

Anchors, No. of

Cables (State in