

WB=CellDBorDBa feet; uE&B feet; f
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thickness of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Particulars of Classification
precisely as in Reg.
CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.

3m.3.15.

POSTPONED SURVEYS.

Case of the Steel S.S. "Kaitangata"

No. 63 in Reg. Bk. 1981/1219 tons, Built 1907-10 mo.

Classed +100/71 Owners Union S.S. Co. of New Zealand Ltd.

ss ho 1-12 7.14 TS 7.12 Port of Registry Dunedin, N.Z.

BS 7.14 +LMC 7.12

Survey due Scrub shaft survey due July 1914

The usual preliminary notice in regard to this survey was sent to the Owners to which no reply was received. The Dunedin surveyor was therefore requested on the 13th January to ascertain what definite arrangements the Owners propose making to have the inspection held but no reply has yet been received at this office.

*Submitted to the Dunedin Surveyor
be again written to. R.M.S.
10.5.15*

Committee's Minute TUE. MAY. 11. 1915

Decision Referred

Survey 7.14 noted