

1

17 JUL 1923

Sent to Chief Surveyors 4. 7. 23.

Received from Chief Surveyors

VESSEL'S NAME Wood & White night

Report Lon.

No. 86699a

For the ~~SHIP~~ SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey Tail Shaft

When due 6. 23

The examination of the screw shaft became due in 6. 23.

The Owners do not wish to retain the vessel's class. It is submitted that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof, indicating that the class has been withdrawn at the Owners request.

Withdraw class.
Insert ...

W.D. 4/7/23
M.D.
Lloyd's Register Foundation
W1484-0003