

or

Received from Chief Ship Surveyor

Wood Sc. Drifter "FOUNTAIN" Rpt. H/L No. 31874

Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also by any exceptional features in connection with the case, so that the Classing Committee may have all the salient points of endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

First Entry

□ Bower and Kedge Anchors supplied by Admiralty, no produced.

is submitted this vessel appears worthy to be classed as 11A.1. "For Fishing Purposes," as recommended.

years table A

— years mixed materials

1 A.1. "For Fishing Purposes."

3 & 12 years mats.

1 Dk.

Lloyd's A & C.P.



ars.  
© 2021 10-6-20

Lloyd's Register  
Foundation