

2 MAR 1945

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

L'S NAME "BERAKIT" REPORT Syd. No. 19064

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This Dutch vessel was built in 1924 and classed with the Germanischer Lloyd or other Society.

The SYDNEY Surveyors report (12.42) the vessel examined afloat on account of damage through heavy weather and repairs effected to numerous deck fittings.

A GENERAL EXAMINATION has been carried out in accordance with Circular 1772.

The deck plating was found generally in good comdition but somewhat worn abreast hatchways but efficient.

It is submitted the vessel appears worthy to have notations of 100A1 Classification Contemplated and 'Examined 12.42' valid for 12 months assigned as recommended.

- 100A1
- "Class contemplated"
- "Examined 12.42 W.S.S."

BBM



13.43.2020

Lloyd's Register Foundation

W150-0172