

*Received from Chief Surveyors*

## Report

Rev.

No. 438  
440

**For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~**


(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/02.*)

When due

100. A. 1. (Steel) Shelter Deck with foreboard } After examination in  
Camping petroleum in bulk } Dry dock.

2 Dks (Steel) ~ Shelter Dk (Steel) ~ Welframes, longitudinal framing  
Cell DB in way of oil bunkers 17' 0" E x B 71' 3 1/2" E, DTh 50' 6" E, FPT 177" E, APT 26" E  
FK, 17 BH (3 to Shelter Dk, 10 to upper Dk, 4 to 2<sup>nd</sup> Dk), pt Cens, A & C.  
Kichy Aff.

S.O. (7) 6/2/32.



© 2020

110-2-22

Lloyd's Register  
Foundation  
150-0191

W150-0191