

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

19

When handed in at Local Office

19

Port of

London

No. in
Reg. Book.

Survey held at

Date, First Survey

Last Survey

19

5744

on the Wood, Iron or Steel Lc. "CONDOR"

(No. of Visits)

Master

TONNAGE:-

GROSS 2753

UNDER DEK 2218

NET 535

Built at

Pittsburgh O.

By whom Lt. Lakes Eng. Works

YEAR.

MONTH.

Owners

Kronstad & Brackhus - Ingis. Port belonging to

When 1916

Bergen

Owners' Address

(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

total capacity

tons. FPT

tons; APT

tons; MT

feet

feet;

tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 15175

Port

Hann

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.Years
Assigned
expired.Machinery and Boiler
Surveys
(including date of N.B., if any).

+100ft

8 20

Lub 11.16

15 8.20 CL

Large Ballast not fitted.

Society's Freeboard (if assigned) as
painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—

Renewed

Removed and Faird or Repaired

Faird or Repaired in place

Plates.

Frames.

E. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:—

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Waterways

Coamings

Beams & Fastenings

Outside Plating

Caulking of ditto

Rivets

Breasthooks & Crutches

Transoms

Frames

Reverse Frames

Floors

Keelsons

Stringers

Inner Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

(State which.)

Rudder

Steering gear and its connections

Windlass

Have Pumps now been examined and found effi-

cient?

Have Sluice Valves now been examined and found

efficient?

Have Watertight Doors now been examined and found

efficient?

Have Ventilators and their Coamings been examined

and found efficient?

Dblg. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking

Treennails

Breasthooks & Stemson

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shelves

Salting

(State if examined.)

Copper, or Y.M. of Wood Vessels.

(State if on Felt.)

When put on, Month

Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

" length

(on board)

" Rule length

Hawser & Warps

Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptnd15, &c."

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) (per Sec. 28) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,

19

Committee's Minute

TUE. NOV. 7 1922

Character Assigned

Expunge class

with Red line

Surveyor to Lloyd's Register of Shipping.

General Committee

Thursday 9th November 1922

Decision of Classing

Conc. confirmed

To Certificate required? If so, to be sent to

1005-0052