

1

Sent to Chief Surveyors 3 1. 17

Received from Chief Surveyors

VESSEL'S NAME

Condorex
Sheers BeguaReport Cleveland No. 75

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement,"—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Eng--

When due

❖ 100 A-1. (Steel)

15K (Steel)

Topside tanks

Cell DB 209. 5956.

Topside tanks 3826. F.P.T. 180E A.P.T. 506

FK. 4BH. Cam

A.P.P. P.121. F 25. Truly att.

M
4. 1. 17

It is concluded reversed bars are fitted to the
stiffeners on after peak bulkhead as shown on sketch appended,
but they should state if this is so.

"The Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be printed in the Register Book.

Wlfts 1, 11. 18 damage

© 2021

Lloyd's Register
Foundation