

LLOYD'S REGISTER OF SHIPPING,
454 CALIFORNIA STREET,

LLOYD'S REGISTER
NEW YORK

SAN FRANCISCO

REC'D OCT 17 1918

October 12th, 1918.

ANS'D _____

The Secretary,
NEW YORK.

[Handwritten signatures and initials]

Dear Sir,

In reply to your letter of the 1st inst., relative to the S.S. "ACCOMAC", San Francisco Report No. 2778, I have to advise you that the screw shaft is not fitted with a continuous liner, the liner being in three pieces and burned at the joints as required by the Rules. The same applies to the S.S. "WAKULLA", San Francisco Report No. 2783, S.S. "WAMPUM", San Francisco Report No. 2784, S.S. "WASSAIC", San Francisco Report No. 2785, and the S.S. "WEST GALOC", San Francisco Report No. 2814, respectively Nos. 2, 3, 4, and 5 of the Los Angeles Shipbuilding & D.D. Co.

Yours very truly,

J. Blackett

JSB:MA.



© 2021

Lloyd's Register
Foundation

W1505-0080